Work Orde Wednesday, Nov					Lid	for	eng	ng. Page 1			
Item ID: Revision ID:	D3914-041	id Assembly (350)	,	Accept	Cust Item ID: Customer:			S	etup Sta		
Item Name: Start Date: Required Date: Reference:	11/10/2010	Start Qty: 1.00 Req'd Qty: 1.00							-	- (/888348781818	
Approvals:	Process Plan	n:_MF	Date: <u> 0- - 0</u>	Tooling: SPC (Y/N):		nte:		R	un Sta Sto		
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty		nsp. Stamp
Draw Nbr		ision Nbr								= *	
D3914 100 Large Fab	В	Weld per dwg A/R S.S. Large Fab Memo	rod Batch: ///585	0.00					Opl	01116	
Large Fab		2- weld hing ***inspect b 3- tack weld	ribs, weld as per dwg D39 e (3) and Mounting bracket efore welding mesh*** mesh on basket as per dwg te to place mesh correctly or ***	s as per dwg D3914 D3914	olate before) _			*		
110	£	QC9- Inspect visual per (QSI004- Fusion Welds	0.00		E			d		
QC Quality Control		Memo		0.00	7210	> 1 L	0/		9		WARTHER STOCKHOLD STOCKHOL
		'n.									



Work Orde Wednesday, Nov											Page 2		
Item ID: D3914-041 Revision ID:					Accept					S	Setup Star	1 18811181	
	11/10/2010	Start Qty: 1.00 Req'd Qty: 1.00	11990			.*	Cust Item I	D:			Sto	P	
		n;	Date:		Toolin	-	Date:			. Б	Run Stai Sto		
Sequence ID/ Work Center II 120 QC Quality Control	•	Operation Description QC6- Inspect dimension Memo	is to drawing	en	0.00	Up/ 1 Hours — inspecto Duy. Siolizla		Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Powder Coating		Start Time:	ides of hinge prior herature:		0.00 0.00 ercoat***					1.	B	l 10-	12-1
140		Wing Walk as per dwg	OSIONS A A Batch	11110	795000	-> U	/ 10 1	1-1					

Hand Finishing

0.00

1- Mask data plate and apply wing walk on outside surface of mesh as per dwg

Work Order ID 63715

Wednesday, November 10, 2010 1:34:17 PM



Page 3

Item ID:

D3914-041

Accept

Setup Start

Stop

Revision ID:

Item Name:

Long Basket Lid Assembly (350)

Start Date:

11/10/2010

Start Qty: 1.00

Required Date: 11/17/2010

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

OC:

Process Plan:

Date:

Tooling:

Date:

Run

Start

Date: _____ SPC (Y/N): Date:

Stop

Sequence ID/ Work Center ID

150

QC Quality Control Operation Description

OC3- Inspect Part Finish

Memo

Run Hours

0.00

Set Up/

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

160

Packaging

Packaging

Identify as per dwg & Stock Location: 6 - A

Memo

0.00

0.00

170

QC21- Final Inspection - Work Order Release

0.00

QC

Memo

0.00

Quality Control

Wednesday, November 10, 2010 1:34:17 PM

Work Order ID: 63715

Parent Item:

D3914-041

Parent Item Name: Long Basket Lid Assembly (350)



Start E .. te: 11/10/2010

Required Datc. 11/17/2010

Start Qty: 1.00

Required Qty: 1.00

IDD Rev: A new issue DD 10.03.10 verified by EC

IDD ReveR

	Comments:	as per dwg revB D				IPP	IPP Rev:B							
	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
	D2581 Mounting Bracket		Manufactured	No			100	Each	43.0000	2	2	Cpl,	0.11-16	
					Locatio	<u>n</u>	Loc	<u>Qty</u>	Loc Code			·		
					, WA	·		43						
						61953 63493		20 23	,	<u>.</u>	3			
	D2728-3		Manufactured	No			140	Each	0.0000	1	1			
	Dart Logo label							M115	0 20) Y	الكال	10	140)
1	D3914-1		Manufactured	No			100	Each	2.0000	2	2		pl	0.11.16
					Locatio	<u>n</u>	Loc	Oty	Loc Code			_	V	
					WA			2		•	7063	716-	→ a	•
						60703		2			9 9 9	-	1	
	. twellin reme Witte fale: likit giet ties.		Manufactured	No			100	Each	2.0000	2 .	2	L.	pli	»·/(·/b
	Rib				Locatio	<u>n</u>	Loc	Oty	Loc Code		3 6	7 - F1 7 8		~
					WA			2			40.	2414-		-97
						60676		2				_		

Wednesday, November 10, 2010 1:34:17 PM

Work Order ID: 63715

Parent Item:

D3914-041

Parent Item Name: Long Basket Lid Assembly (350)



Start Jate: 11/10/2010

Required 2 ate: 11/17/2010

Start Qty: 1.00

Required Qty: 1.00

3

D4016-3

Hinge Half, Lid

✓ D4018-5

D4020-5

Manufactured

Manufactured No

No

Location Loc Qty ST116 60723 WA 63256

100

100 Each

Each

6.0000

10.0000

Loc Code

Manufactured No Location Loc Oty Loc Code WA 59929 100

2.0000 Each

Mesh (350 Basket Long, Lid)

No Manufactured

Location Loc Qty Loc Code WA 60643 60733

100 Each 3.0000

363718

Location Loc Otv Loc Code WA 56050 60734 2

Data Plate

D4021-3

Wednesday, November 10, 2010 1:34:17 PM

Shop Packet Print

Page 2

Wednesday, November 10, 2010 1:34:17 PM

Work Order ID: 63715

Parent Item:

D3914-041

Parent Item Name: Lc., g Basket Lid Assembly (350)



St.:rt Date: 11/10/2010

Required Date: 11/17/2010

Start Qty: 1.00

Required Oty: 1.00

100

100

D4035-041

Lid Rib Assembly, Fwd (350 Basket)

Location WA

61066

Loc Oty

Each

Each

Loc Code

2.0000

2.0000

D4035-043

Lid Rib Assembly, Aft (350 Basket)

Manufactured No

Manufactured

No

Location

WA

61067

Loc Qty 2 2 Loc Code







